



DITCH BACK-FILLED FOR DRIVEWAY WITH NO CULVERT: WATER EVIDENT IN REMAINING DITCH?

DITCHES AND CULVERTS TO BE CLEARED

DITCHES AND CULVERTS TO BE CLEARED

EA HAVE CLEARED DEBRIS AND VEGETATION FROM LIDEN BROOK

FARMING PRACTICES INFLUENCE SURFACE WATER MOVEMENTS; HOWEVER NO DITCHES OR CULVERTS AROUND THIS FIELD

OLD DITCH SYSTEM - BACKFILLED BY LANDOWNERS - MAY HAVE FOLLOWED ROUTE OF OLD SWINDON ROAD

DITCH ROUTED IN NORTHERLY DIRECTION. THIS MAY BE BENEFICIAL TO MODRLEAZE

INVESTIGATE POSSIBILITY OF CULVERT/ OLD DRAINAGE SYSTEM?

INVESTIGATE OLD HIGHWAY DRAINAGE SYSTEM AND/OR PRIVATE SYSTEM AROUND (GMF) PROPERTY, CCTV, JET AND REINSTATE

DITCHES AND CULVERTS TO BE CLEARED

| | |
|------------------------------|--|
| | |
| Project Title | |
| Wanborough Flood Assessment | |
| Project Engineer | |
| Carl Collins | |
| Contact | |
| 07881 456610 01249 714321 | |
| Approved by : | |
| Title : A3 view 4 | |
| Revision : 2 | |

| | |
|---------------------------------------|--|
| KEY | |
| Main River | |
| Land Drain | |
| Ditch | |
| Highways drainage | |
| Storage | |
| Water Course Improvement | |
| Properties with history of flooding | |
| Properties with High Risk of Flooding | |
| Run off from hills | |
| Overflowing drain | |